

Make	Model	Year	OEM Sensor Part No.	OEM Service Kit	Replacement Sensor #	Replacement Service Kit	Torque in-lbs	Torque N.m.	Special Instructions	
LINCOLN	AVIATOR	2005-2003	4L2T 1A150-BA	SB-20002	SB-20096	SB-20002	44	5		
	MARK LT	2008-2007			SB-28385		27	3		
	MKX	2008-2007			SB-28385		27	3	W/Chrome Plated Alnm, Wheels	
					SB-28390		27	3	W/O Chrome Plated Alnm. Wheels	
	MKZ	2008-2007			SB-28385		27	3		
	NAVIGATOR	2008-2007				SB-28390				
			2006-2005	5L1Z 1A150-AA	SB-20002	SB-20135	SB-20002	44	5	
			2004-2003	4L2T 1A150-BA	SB-20002	SB-20096	SB-20002	44	5	
TOWN CAR	2008-2006				SB-28385					