

<b>Make</b>	<b>Model</b>	<b>Year</b>	<b>OEM Sensor Part No.</b>	<b>OEM Service Kit</b>	<b>Replacement Sensor #</b>	<b>Replacement Service Kit</b>	<b>Torque in-lbs</b>	<b>Torque N.m.</b>
<b>ACURA</b>	MDX	2006-2004	06421 S3V A02	SB-20036	SB-28981	SB-20036	35	4
	RL	2008-2005	06421 S3V A02	SB-20036	SB-28981	SB-20036	35	4
	TL	2008-2005	06421 S3V A02	SB-20036	SB-28981	SB-20036	35	4