

Make	Model	Year	OEM Sensor Part No.	OEM Service Kit	Replacement Sensor #	Replacement Service Kit	Torque in-lbs	Torque N.m.	Special Instructions	
GMC	ACADIA	2007		SB-20030	SB-20158	SB-20004	62	7		
	CANYON	2008-2007	15122618	SB-20006	SB-20131	SB-20006	62	7		
	ENVOY	2008-2006	25774006	SB-20004	SB-20116	SB-20004	62	7		
	SIERRA SERIES PICKUPS		2008	15254101	SB-20008	SB-20153	SB-20008	62	7	W/Single Rear Wheels
			2007	15254101	SB-20008	SB-20153	SB-20008	62	7	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic
					SB-20015	SB-20158	SB-20015	62	7	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic
				15114379	SB-20004	SB-20107	SB020004	62	7	Classic
			2006-2005	15114379	SB-20004	SB-20107	SB-20004	62	7	
			2004	15136883	SB-20004	SB-20115	SB-20004	62	7	
	YUKON		2008	15254101	SB-20008	SB-20153	SB-20008	62	7	
			2007	15254101	SB-20008	SB-20153	SB-20008	62	7	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
					SB-20015	SB-20158	SB-20015	62	7	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem
			2006-2005	15114379	SB-20004	SB-20107	SB-20004	62	7	
			2004	15136883	SB-20004	SB-20115	SB-20004	62	7	