

Make	Model	Year	OEM Part No.	Sensor	OEM Service Kit	Replacement Sensor #	Replacement Service Kit	Torque in-lbs	Torque N.m.	Special Instructions
HONDA	PILOT	2008-2006	06421 A02	S3V	SB-20036	SB-28981	SB-20036	35	4	
		2005	06421 A01	S9V	SB-20035	SB-28982	SB-20035	35	4	LX; W/Long Stem Valve
			06421 A02	S3V	SB-20036	SB-28981	SB-20036	35	4	EX
			06421 A02	S3V	SB-20036	SB-28981	SB-20036	35	4	LX; W/Short Stem Valve
	RIDGELINE	2008-2007	06421 A02	S3V	SB-20036	SB-28981	SB-20036	35	4	RTL,RTS,RTX
		2008-2006	06421 A01	S9V	SB-20035	SB-28982	SB-20035	35	4	RT
		2006	06421 A02	S3V	SB-20036	SB-28981	SB-20036	35	4	RTL,RTS