

Make	Model	Year	OEM Sensor Part No.	OEM Service Kit	Replacement Sensor #	Replacement Service Kit	Torque in-lbs	Torque N.m.	Special Instructions
HYUNDAI	ENTOURAGE	2008-2007		SB-20037		SB-20037	31-40	3.5-4.5	W/43mm Silver Insert
				SB-20038		SB-20038	31-40	3.5-4.5	W/48mm Green Insert
				SB-20039		SB-20039	31-40	3.5-4.5	W/ 49mm Black Insert
				SB-20040		SB-20040	31-40	3.5-4.5	W/51mm Orange Insert
	SANTA FE	2008-2007		Same as Entourage		Same as Entourage	31-40	3.5-4.5	Same as Entourage
	SONATA	2008-2007	529331FA00	SB-20036	SB-28983	SB-20036	31-40	3.5-4.5	
	TUCSON	2008-2006	529331FA00	SB-20036	SB-28983	SB-20036	31-40	3.5-4.5	
	VERACRUZ	2008-2007		Same as Entourage		Same as Entourage	31-40	3.5-4.5	Same as Entourage