

Make	Model	Year	OEM Sensor Part No.	OEM Service Kit	Replacement Sensor #	placement Service	Torque In-lbs	Torque N.m.	Special Instructions	
MERCEDES-BENZ	C300	2008	004 542 15 18	SB-20016	SB-28214	SB-20016				
	C350	2008-2007	004 542 15 18	SB-20016	SB-28214	SB-20016				
	CL55	2006-2001			SB-20037		SB-20037	35	4	W/43mm Silver Insert
					SB-20038		SB-20038	35	4	W/48mm Green Insert
					SB-20039		SB-20039	35	4	W/ 49mm Black Insert
					SB-20040		SB-20040	35	4	W/51mm Orange Insert
	CL500	2006-2000		Same as CL 55		Same as CL 55	35	4	Same as CL 55	
	CL550	2007		SB-20017		SB-20017			W/315MHz Sensor	
	CL600	2007		SB-20017		SB-20017			W/315MHz Sensor	
		2006-2001		Same as CL 55		Same as CL 55	35	4	Same as CL 55	
	CL63	2007		SB-20017		SB-20017			W/315MHz Sensor	
	CL65	2006-2005		Same as CL 55		Same as CL 55	35	4	Same as CL 55	
	CLK350	2008-2007	004 542 15 18	SB-20016	SB-28214	SB-20016				
	CLK550	2008-2007	004 542 15 18	SB-20016	SB-28214	SB-20016				
	CLK63	2008-2007	004 542 15 18	SB-20016	SB-28214	SB-20016				
	CLS55	2006		SB-20017		SB-20017	53	6		
	CLS63	2007		SB-20017		SB-20017				
	CLS500	2006		SB-20017		SB-20017	53	6		
	E320	2007-2006		SB-20017		SB-20017				
		2005-2001		Same as CL 55		Same as CL 55	35	4	Same as CL 55	
	E350	2007		SB-20017		SB-20017				
	E55	2006		SB-20017		SB-20017				
		2005-1999		Same as CL 55		Same as CL 55	35	4	Same as CL 55	
	E500	2006		SB-20017		SB-20017				
		2005-2003		Same as CL 55		Same as CL 55	35	4	Same as CL 55	
	E550	2007		SB-20017		SB-20017				
	E63	2007-2006		SB-20017		SB-20017				
	G500	2008-2007	004 542 15 18	SB-20016	SB-28214	SB-20016				
	G55	2008-2007	004 542 15 18	SB-20016	SB-28214	SB-20016				
	ML63	2007		SB-20017		SB-20017	53	6		
ML350	2007-2006		SB-20017		SB-20017	53	6			
ML500	2007-2006		SB-20017		SB-20017	53	6			
R320	2007		SB-20017		SB-20017	53	6			

R350	2007-2006		SB-20017		SB-20017	53	6	
S55	2006-2001		Same as CL 55		Same as CL 55	35	4	Same as CL 55
S63	2007		SB-20017		SB-20017			
S65	2007		SB-20017		SB-20017			
	2006		Same as CL 55		Same as CL 55	35	4	Same as CL 55
S350	2006		Same as CL 55		Same as CL 55	35	4	Same as CL 55
S430	2006-2000		Same as CL 55		Same as CL 55	35	4	Same as CL 55
S500	2006-2000		Same as CL 55		Same as CL 55	35	4	Same as CL 55
S550	2007		SB-20017		SB-20017			W/315MHz Sensor
S600	2007		SB-20017		SB-20017			
	2006-2003		Same as CL 55		Same as CL 55	35	4	Same as CL 55
SL55	2007		SB-20017		SB-20017			
	2006-2003		Same as CL 55		Same as CL 55	35	4	Same as CL 55
SL65	2007-2006		SB-20017		SB-20017			
	2005		Same as CL 55		Same as CL 55	35	4	Same as CL 55
SL500	2006		SB-20017		SB-20017			
	2005-2001		Same as CL 55		Same as CL 55	35	4	Same as CL 55
SL550	2007		SB-20017		SB-20017			
SL600	2007-2006		SB-20017		SB-20017			
	2005		Same as CL 55		Same as CL 55	35	4	Same as CL 55
	2003-2001		Same as CL 55		Same as CL 55	35	4	Same as CL 55
SLK280	2008	004 542 15 18	SB-20016	SB-28214	SB-20016			
	2007	004 542 15 18	SB-20016	SB-28214	SB-20016	May & Newer		
		004 542 15 18	SB-20017	SB-28214	SB-20017	April & Older		
SLK350	2008	004 542 15 18	SB-20016	SB-28214	SB-20016			
	2007	004 542 15 18	SB-20016	SB-28214	SB-20016	May & Newer		
		004 542 15 18	SB-20017	SB-28214	SB-20017	April & Older		
SLK55	2008	004 542 15 18	SB-20016	SB-28214	SB-20016			
	2007	004 542 15 18	SB-20016	SB-28214	SB-20016	May & Newer		
		004 542 15 18	SB-20017	SB-28214	SB-20017	April & Older		
SLR MCLAREN	2006-2004		Same as CL 55		Same as CL 55	35	4	Same as CL 55