

Make	Model	Year	OEM Service Kit	Replacement Sensor #	Replacement Service Kit	Torque lbs	In-Torque N.m.	Special Instructions
SCION	TC	2008-2007	SB-20032	SB-28365	SB-20032	35	4	
		2006	SB-20032	SB-28365	SB-20032	35	4	May & Newer
	XB	2008	SB-20032	SB-28365	SB-20032	35	4	