

Make	Model	Year	OEM Service Kit	Replacement Sensor #	Replacement Service Kit	Torque in-lbs	Torque N.m.	Special Instructions
TOYOTA	4 RUNNER	2008-2007	SB-20032	SB-28365	SB-20032	35	4	W/Valve Cap
			SB-20032	SB-28370	SB-20032	35	4	W/O Valve Cap
		2006	SB-20032	SB-28365	SB-20032	35	4	W/Valve Cap; June & Newer
			SB-20031	SB-28365	SB-20031	35	4	W/Valve Cap; Feb.2006 Thru March 2006
			SB-20032	SB-28370	SB-20032	35	4	W/O Valve Cap; June & newer
			SB-20031	SB-28335	SB-20031	35	4	W/O Valve Cap; Feb. 2006 Thru May 2006
			SB-20031	SB-28345	SB-20031	35	4	Jan. 31 -May
			SB-20032	SB-28345	SB-20032	35	4	June & Newer
		2005-2003	SB-20031	SB-28345	SB-20031	35	4	
	AVALON	2008-2007	SB-20032	SB-28360	SB-20032	35	4	
		2006	SB-20032	SB-28360	SB-20032	35	4	August & Newer
	CAMRY	2008-2007	SB-20032	SB-28365	SB-20032	35	4	Models Made in Japan
			SB-20032	SB-28360	SB-20032	35	4	Models Made in USA
	COROLLA	2008	SB-20032	SB-28365	SB-20032	35	4	Models Made in Japan
			SB-20032	SB-28360	SB-20032	35	4	Models Made in USA
		2007	SB-20032	SB-28365	SB-20032	35	4	Models Made in Japan; June & Newer
			SB-20032	SB-28360	SB-20032	35	4	Models Made in USA; June & Newer
	FJ CRUISER	2008	SB-20032	SB-28365	SB-20032	35	4	
	HIGHLANDER	2008	SB-20032	SB-28365	SB-20032	35	4	
		2007	SB-20032	SB-28365	SB-20032	35	4	May & Newer
	LAND CRUISER	2008-2007	SB-20032	SB-28365	SB-20032	35	4	
		2006-2005	SB-20031	SB-28365	SB-20031	35	4	
	MATRIX	2008	SB-20032	SB-28365	SB-20032	35	4	Models Made in Japan
			SB-20032	SB-28360	SB-20032	35	4	Models Made in USA
		2007	SB-20032	SB-28365	SB-20032	35	4	Models Made in Japan; June & Newer
			SB-20032	SB-28360	SB-20032	35	4	Models Made in USA; June & Newer
	PRIUS	2008-2006	SB-20032	SB-28365	SB-20032	35	4	
RAV4	2008-2007	SB-20032	SB-28370	SB-20032	35	4		
	2006	SB-20032	SB-28365	SB-20032	35	4		

	SEQUOIA	2008-2005	SB-20031	SB-28305	SB-20031	35	4	W/Alloy Wheels
			SB-20031	SB-28305	SB-20031	35	4	W/Steel Wheels; W/20 Deg. Angled Valve Sensor
			SB-20031	SB-28300	SB-20031	35	4	W/Steel Wheels; W/40 Deg. Angled Valve Sensor
	SOLARA	2008-2007	SB-20032	SB-28360	SB-20032	35	4	May & Newer
		2006	SB-20032	SB-28360	SB-20032	35	4	May & Newer
	TACOMA	2008-2007	SB-20032	SB-28360	SB-20032	35	4	W/20 Deg. Angled Valve Sensor
			SB-20032	SB-28380	SB-20032	35	4	W/40 Deg. Angled Valve Sensor
		2006	SB-20032	SB-28360	SB-20032	35	4	W/20 Deg. Angled Sensor; August & Newer
			SB-20031	SB-28355	SB-20031	35	4	W/20 Deg. Angled Sensor; July & Older
			SB-20032	SB-28380	SB-20032	35	4	W/40 Deg. Angled Valve Sensor; August & Newer
		2005	SB-20031	SB-28380	SB-20031	35	4	W/40 Deg. Angled Valve Sensor; July & Older
			SB-20031	SB-28355	SB-20031	35	4	W/20 Deg. Angled Valve Sensor; Nov. 30 & Older
			SB-20031	SB-28305	SB-20031	35	4	W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer
			SB-20031	SB-28380	SB-20031	35	4	W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer
		TUNDRA	2006	SB-20031	SB-28305	SB-20031	35	4
	SB-20031			SB-28300	SB-20031	35	4	W/40 Deg. Angled Valve Sensor; Oct. 31 & Older
	2005		SB-20031	SB-28305	SB-20031	35	4	W/20 Deg. Angled Valve Sensor
			SB-20031	SB-28300	SB-20031	35	4	W/40 Deg. Angled Valve Sensor
	YARIS	2008-2007	SB-20032	SB-28365	SB-20032	35	4	