

Make	Model	Year	OEM Sensor Part No.	OEM Service Kit	Replacement Sensor #	Replacement Service Kit	Torque In-lbs	Torque N.m.
VOLVO	C30(433 Mhz)	2008	30666931	DI-1050K	DI-1044	DI-1050K	44	
	C70(433 Mhz)	2008-2007	30666931	DI-1050K	DI-1044	DI-1050K	44	
	S40(433 Mhz)	2008-2007	30666931	DI-1050K	DI-1044	DI-1050K	44	
	S60	2007-2004	8651700	SB-20010	SB-20156	SB-20010	44	5
	S80	2006-2004	8651700	SB-20010	SB-20156	SB-20010	44	5
	S80(433 Mhz)	2008-2007	30666931	DI-1050K	DI-1044	DI-1050K	44	5
	V50(433 Mhz)	2008	30666931	DI-1050K	DI-1044	DI-1050K	44	
	V70(433 Mhz)	2008-2004	30748354	DI-1050K	DI-1044	DI-1050K	44	
	V70	2007-2004	8651700	SB-20010	SB-20156	SB-20010	44	5
	XC70(433 Mhz)	2008-2004	30748354	DI-1050K	DI-1044	DI-1050K	44	
	XC70	2007-2004	8651700	SB-20010	SB-20156	SB-20010	44	5
	XC90	2007-2004	8651700	SB-20010	SB-20156	SB-20010	44	5