

Make	Model	Year	OEM Sensor Part No.	OEM Service Kit	Replacement Sensor #	Replacement Service Kit	Torque In-lbs	Torque N.m.
HUMMER	H2	2008	15254101	SB-20008	SB-20153	SB-20008	62	7
	H3	2008-2006	15122618	SB-20006	SB-20131	SB-20006	62	7