

| <b>Make</b> | <b>Model</b> | <b>Year</b> | <b>OEM Sensor Part No.</b> | <b>OEM Service Kit</b> | <b>Replacement Sensor #</b> | <b>Replacement Service Kit</b> | <b>Torque In-lbs</b> | <b>Torque N.m.</b> | <b>Special Instructions</b> |
|-------------|--------------|-------------|----------------------------|------------------------|-----------------------------|--------------------------------|----------------------|--------------------|-----------------------------|
| <b>KIA</b>  | AMANTI       | 2008-2007   | 958104D100                 | SB-20036               | SB-28983                    | SB-20036                       | 31-40                | 3.5-4.5            |                             |
|             | SEDONA       | 2008-2006   |                            | SB-20037               |                             | SB-20037                       | 31-40                | 3.5-4.5            | W/43mm Silver Insert        |
|             |              |             |                            | SB-20038               |                             | SB-20038                       | 31-40                | 3.5-4.5            | W/48mm Green Insert         |
|             |              |             |                            | SB-20039               |                             | SB-20039                       | 31-40                | 3.5-4.5            | W/ 49mm Black Insert        |
|             |              |             |                            | SB-20040               |                             | SB-20040                       | 31-40                | 3.5-4.5            | W/51mm Orange Insert        |
|             | SORENTO      | 2008-2007   | 958104D100                 | SB-20036               | SB-28983                    | SB-20036                       |                      |                    |                             |
|             | SPORTAGE     | 2008-2006   | 958104D100                 | SB-20036               | SB-28983                    | SB-20036                       | 31-40                | 3.5-4.5            |                             |
|             |              | 2005        | 958104D100                 | SB-20036               | SB-28983                    | SB-20036                       | 31-40                | 3.5-4.5            | June 15,2005 & Newer        |