

Make	Model	Year	OEM Service Kit	Torque in-lbs	Torque N.m.
MAZDA	3	2008-2004	SB-20030	62-70	7.5-8.5
	5	2008-2006	SB-20030	67-75	7.5-8.5
	6	2006-2005	SB-20030	62-75	7.5-8.5
	CX-7	2008-2007	SB-20030		
	MX-5 MIATA	2008-2006	SB-20030	67-75	7.5-8.5
	RX-8	2008-2004	SB-20030	62-75	7.5-8.5